



**RIGEL MEDICAL**  
GMC-INSTRUMENTS GROUP

## Why am I getting an error when using the PULS-R?

If the error message "Fitted SpO2 adapter does not match selected technology type" this can be resolved by selecting a PULS-R option in technology type. For example, change Nellcor (standard) to Nellcor (PULS-R) in the menu.

Ensure that both blue lights are on and the set up is as displayed in the image below.

If you require more help, please contact us at

<https://www.seaward.com/gb/enquire/>.

